

Water Utility Services, Inc.

P.O. Box 2628
Spring, Texas 77383
281-290-0704

Client: Severn Trent Environmental Services, Inc.
16337 Park Row
Houston, Texas 77084
ElizaBeth Reeves

Test Report - Nitrification Monitoring

PROJECT LOCATION: Bella Vita
COLLECTION DATE: 08/16/11
SAMPLE TYPE: Grab
COLLECTED BY: RF
SAMPLE MATRIX: Potable Water

SAMPLE LOCATION	Chlorine mg/L	Monochloramine mg/L	Free Ammonia mg/L	Nitrate-N mg/L	Nitrite-N mg/L	HPC* MPN/ml	Total Coliform
1602 Berlino Dr	0.29	< 0.10	0.10	0.405	0.215	738	not found
1627 Berlino Dr	< 0.10	< 0.10	0.06	0.314	0.246	440	not found
2108 W. Marsala	0.31	< 0.10	0.08	0.406	0.194	287	not found
2406 S. Venice	2.02	1.95	0.05	< 0.10	0.019	56	not found

Method: Hach 8167 Hach 10200 Hach 10200 Hach 8192 Hach 8507 SimPlate Colitag
Analyst: RF RF RF KWM KWM BC SG
Date: 08/16/11 08/16/11 08/16/11 08/16/11 08/16/11 08/16/11 08/16/11

* HPC - Heterotrophic Plate Count, MPN - most probable number

Nitrification is widespread - flushing recommended.

Steve Grychka

Steve Grychka
Laboratory Director