



EASTEX ENVIRONMENTAL LABORATORY, INC.

P. O. Box 1089
Coldspring, Texas 77331
(936) 653-3249 * (800) 525-0508



P. O. Box 631375
Nacogdoches, Texas 75963-1375
(936) 569-8879

City of Pearland
3519 Liberty
Pearland, TX 77581

LABORATORY ANALYSIS REPORT (8/16 Joint tests with BV)

(TESTS CONDUCTED AT HYDRANTS)

*This is late lab data.
ie. Transporting to LAB.*

Project ID: Bellavita Samples

Sample Number: C1138448-01
Site: 2413 Modena Ct
Collect Date: 8/16/2011
Collect Time: 10:59 AM
Collector: ts
SampleType: Grab

Test	*	Result	Units	Tech	Date	Time	Method
Chlorine	P	1.4	mg/L	DSB	8/17/2011	11:00:00 A	SM 4500-Cl F
Nitrate - N	N	3.8	mg/L	DSB	8/17/2011	12:45:00 P	SM 4500 D
Nitrite as N	A	<0.02	mg/L	BAD	8/17/2011	3:00:00 PM	SM 4500 NO3 F

Sample Number: C1138448-02
Site: Bellavita/Scarsdale
Collect Date: 8/16/2011
Collect Time: 10:59 AM
Collector: ts
SampleType: Grab

Test	*	Result	Units	Tech	Date	Time	Method
Chlorine	P	1.7	mg/L	DSB	8/17/2011	11:00:00 A	SM 4500-Cl F
Nitrate - N	N	3.6	mg/L	DSB	8/17/2011	12:45:00 P	SM 4500 D
Nitrite as N	A	<0.02	mg/L	BAD	8/17/2011	3:00:00 PM	SM 4500 NO3 F

*NELAC Status:A=Accredited N=Accreditation not offered O=Not Accredited P=Approved
Most current versions applicable for methods listed are being used.

The test results in this report relate only to the samples received and the report shall not be reproduced except in full, without the approval of the laboratory.



EASTEX ENVIRONMENTAL LABORATORY, INC.

P. O. Box 1089
Coldspring, Texas 77331
(936) 653-3249 * (800) 525-0508



P. O. Box 631375
Nacogdoches, Texas 75963-1375
(936) 569-8879

City of Pearland
3519 Liberty
Pearland, TX 77581

LABORATORY ANALYSIS REPORT

Sample Number: C1138448-03
Site: ~~1626 Berlino Dr~~ 2112 W. MARSA LA DR,
Collect Date: 8/16/2011
Collect Time: 10:59 AM
Collector: ts
SampleType: Grab


Test	*	Result	Units	Tech	Date	Time	Method
Chlorine	P	1.7	mg/L	DSB	8/17/2011	11:00:00 A	SM 4500-Cl F
Nitrate - N	N	3.8	mg/L	DSB	8/17/2011	12:45:00 P	SM 4500 D
Nitrite as N	A	0.2	mg/L	BAD	8/17/2011	3:00:00 PM	SM 4500 NO3 F

Sample Number: C1138448-04
Site: ~~2112 W Marsala Dr~~ 1626 BERLINO DR,
Collect Date: 8/16/2011
Collect Time: 10:59 AM
Collector: ts
SampleType: Grab

Test	*	Result	Units	Tech	Date	Time	Method
Chlorine	P	0.4	mg/L	DSB	8/17/2011	11:00:00 A	SM 4500-Cl F
Nitrate - N	N	3.9	mg/L	DSB	8/17/2011	12:45:00 P	SM 4500 D
Nitrite as N	A	0.13	mg/L	BAD	8/17/2011	3:00:00 PM	SM 4500 NO3 F

*NELAC Status:A=Accredited N=Accreditation not offered O=Not Accredited P=Approved
Most current versions applicable for methods listed are being used.

The test results in this report relate only to the samples received and the report shall not be reproduced except in full, without the approval of the laboratory.



EASTEX ENVIRONMENTAL LABORATORY, INC.

P. O. Box 1089
 Coldspring, Texas 77331
 (936) 653-3249 * (800) 525-0508



P. O. Box 631375
 Nacogdoches, Texas 75963-1375
 (936) 569-8879

City of Pearland
 3519 Liberty
 Pearland, TX 77581

LABORATORY ANALYSIS REPORT

Sample Number:	C1138448-05
Site:	1603 S Riviera Ct
Collect Date:	8/16/2011
Collect Time:	10:59 AM
Collector:	ts
SampleType:	Grab


Test	*	Result	Units	Tech	Date	Time	Method
Chlorine	P	1.5	mg/L	DSB	8/17/2011	11:00:00 A	SM 4500-Cl F
Nitrate - N	N	3.2	mg/L	DSB	8/17/2011	12:45:00 P	SM 4500 D
Nitrite as N	A	<0.02	mg/L	BAD	8/17/2011	3:00:00 PM	SM 4500 NO3 F

Sample Number:	C1138448-06
Site:	2420 Monaldo Dr
Collect Date:	8/16/2011
Collect Time:	10:59 AM
Collector:	ts
SampleType:	Grab

Test	*	Result	Units	Tech	Date	Time	Method
Chlorine	P	0.8	mg/L	DSB	8/17/2011	11:00:00 A	SM 4500-Cl F
Nitrate - N	N	3.4	mg/L	DSB	8/17/2011	12:45:00 P	SM 4500 D
Nitrite as N	A	0.04	mg/L	BAD	8/17/2011	3:00:00 PM	SM 4500 NO3 F

*NELAC Status:A=Accredited N=Accreditation not offered O=Not Accredited P=Approved
 Most current versions applicable for methods listed are being used.

The test results in this report relate only to the samples received and the report shall not be reproduced except in full, without the approval of the laboratory.



EASTEX ENVIRONMENTAL LABORATORY, INC.

P. O. Box 1089
Coldspring, Texas 77331
(936) 653-3249 * (800) 525-0508



P. O. Box 631375
Nacogdoches, Texas 75963-1375
(936) 569-8879

City of Pearland
3519 Liberty
Pearland, TX 77581

LABORATORY ANALYSIS REPORT

Sample Number: C1138448-07
Site: 1604 N Primavera
Collect Date: 8/16/2011
Collect Time: 10:59 AM
Collector: ts
SampleType: Grab


Test	*	Result	Units	Tech	Date	Time	Method
Chlorine	P	0.9	mg/L	DSB	8/17/2011	11:00:00 A	SM 4500-Cl F
Nitrate - N	N	3.2	mg/L	DSB	8/17/2011	12:45:00 P	SM 4500 D
Nitrite as N	A	<0.02	mg/L	BAD	8/17/2011	3:00:00 PM	SM 4500 NO3 F

Sample Number: C1138448-08
Site: 2416 S Venice Dr
Collect Date: 8/16/2011
Collect Time: 10:59 AM
Collector: ts
SampleType: Grab

Test	*	Result	Units	Tech	Date	Time	Method
Chlorine	P	0.7	mg/L	DSB	8/17/2011	11:00:00 A	SM 4500-Cl F
Nitrate - N	N	3.4	mg/L	DSB	8/17/2011	12:45:00 P	SM 4500 D
Nitrite as N	A	<0.02	mg/L	BAD	8/17/2011	3:00:00 PM	SM 4500 NO3 F

*NELAC Status:A=Accredited N=Accreditation not offered O=Not Accredited P=Approved
Most current versions applicable for methods listed are being used.

The test results in this report relate only to the samples received and the report shall not be reproduced except in full, without the approval of the laboratory.



EASTEX ENVIRONMENTAL LABORATORY, INC.

P. O. Box 1089
Coldspring, Texas 77331
(936) 653-3249 * (800) 525-0508



P. O. Box 631375
Nacogdoches, Texas 75963-1375
(936) 569-8879

City of Pearland
3519 Liberty
Pearland, TX 77581

LABORATORY ANALYSIS REPORT

Qualifiers

C1138448-01	Chlorine	3	Sample analysis performed out of holding time.
C1138448-02	Chlorine	3	Sample analysis performed out of holding time.
C1138448-03	Chlorine	3	Sample analysis performed out of holding time.
C1138448-04	Chlorine	3	Sample analysis performed out of holding time.
C1138448-05	Chlorine	3	Sample analysis performed out of holding time.
C1138448-06	Chlorine	3	Sample analysis performed out of holding time.
C1138448-07	Chlorine	3	Sample analysis performed out of holding time.
C1138448-08	Chlorine	3	Sample analysis performed out of holding time.

James Johnson
James Johnson, Laboratory Director

*NELAC Status:A=Accredited N=Accreditation not offered O=Not Accredited P=Approved
Most current versions applicable for methods listed are being used.

The test results in this report relate only to the samples received and the report shall not be reproduced except in full, without the approval of the laboratory.



EASTEX ENVIRONMENTAL LABORATORY, INC.

P. O. Box 1089
 Coldspring, Texas 77331
 (936) 653-3249 * (800) 525-0508



P. O. Box 631375
 Nacogdoches, Texas 75963-1375
 (936) 569-8879

Quality Control Report

Customer: City of Pearland

Project: Bellavita Samples

Test	Units	Method	Standard		Spike		Duplicate			Original				
			Blank	True	Found	%Rec. Note	%Rec. Note	Lab ID	Result	Dup	RPD	Note	MDL	Order ID
Nitrate - N mg/L SM 4500 D														
	Approve Date													
08/17/11	<0.1	5.0	5.9	118.00	>WL	114%	>WL	C1138450-02	5.7	5.6	1.77	<WL	0.1	C1138448
08/17/11	<0.1	5.0	5.9	118.00	>WL	114%	>WL	C1138450-02	5.7	5.6	1.77	<WL	0.1	C1138448
08/17/11	<0.1	5.0	5.9	118.00	>WL	114%	>WL	C1138450-02	5.7	5.6	1.77	<WL	0.1	C1138448
08/17/11	<0.1	5.0	5.9	118.00	>WL	114%	>WL	C1138450-02	5.7	5.6	1.77	<WL	0.1	C1138448
08/17/11	<0.1	5.0	5.9	118.00	>WL	114%	>WL	C1138450-02	5.7	5.6	1.77	<WL	0.1	C1138448
08/17/11	<0.1	5.0	5.9	118.00	>WL	114%	>WL	C1138450-02	5.7	5.6	1.77	<WL	0.1	C1138448
08/17/11	<0.1	5.0	5.9	118.00	>WL	114%	>WL	C1138450-02	5.7	5.6	1.77	<WL	0.1	C1138448
Nitrite as N mg/L SM 4500 NO3 F														
08/18/11	<0.02	1.0	1.1	112.00	--	119%	--	C1138448-01	1.19	1.16	2.55	--	0.02	C1138448
08/18/11	<0.02	1.0	1.1	112.00	--	119%	--	C1138448-01	1.19	1.16	2.55	--	0.02	C1138448
08/18/11	<0.02	1.0	1.1	112.00	--	119%	--	C1138448-01	1.19	1.16	2.55	--	0.02	C1138448
08/18/11	<0.02	1.0	1.1	112.00	--	119%	--	C1138448-01	1.19	1.16	2.55	--	0.02	C1138448
08/18/11	<0.02	1.0	1.1	112.00	--	119%	--	C1138448-01	1.19	1.16	2.55	--	0.02	C1138448
08/18/11	<0.02	1.0	1.1	112.00	--	119%	--	C1138448-01	1.19	1.16	2.55	--	0.02	C1138448
08/18/11	<0.02	1.0	1.1	112.00	--	119%	--	C1138448-01	1.19	1.16	2.55	--	0.02	C1138448

NOTES: <WL is within warning limits
 >WL is outside warning limits but within control limits
 >CL is outside of control limits